

Annexure D

BUILDING SAFETY CERTIFICATE

No. NA

Dated: 10/05/2026

It is certified that the existing building **Sunbeam Academy, Varanasi** at **Garhwa Ghat Road, Samne Ghat, Bhagwanpur, Varanasi, Uttar Pradesh – 221005** is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)
No. of Floor(s) in the Block	03

The building is owned/occupied by **Sunbeam Academy, Varanasi** at **Garhwa Ghat Road, Samne Ghat, Bhagwanpur, Varanasi, Uttar Pradesh – 221005** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Mr. Shiv Nath Prasad** on **10/05/2026** in the presence of **Mr. Arun Singh, Estate Manager, Sunbeam Academy, Varanasi** and that the building/premises is fit for occupancy for running school with effect from **10/05/2026** for a period of **01** years in accordance:

with rule and subject to compliance of the specific conditions as appended.

1. All standards will be followed in the building.
2. The renewal of this certificate will be done again within the prescribed time period.
3. It will be the responsibility to keep the firefighting systems installed in the building functional before renovation.

Issued on **10/05/2026** by **Mr. Ashutosh Kumar Singh, Executive Engineer Civil, Construction Division-1 Varanasi, Uttar Pradesh**

अधिशारी अशुतोष कुमार
लोक निर्माण विभाग
वाराणसी

Name: **Mr. Ashutosh Kumar Singh**

Designation: **Executive Engineer Civil**

Name & Address of Department/ Office:

Construction Division-1 Varanasi, UP